

To: FERRIS, MELISSA (DNR)[/O=WA.GOV/OU=DNR/CN=RECIPIENTS/CN=MMON490]
Cc: STRICKLER, TIM (DNR)[/O=WA.GOV/OU=DNR/CN=RECIPIENTS/CN=Tstr490]
From: TOBA, DERRICK (DNR)
Sent: Wed 10/6/2010 6:59:21 PM
Subject: RE: creostote

Danielle just mentioned that it was around the mid intertidal level.

From: TOBA, DERRICK (DNR)
Sent: Wed 10/6/2010 11:49 AM
To: FERRIS, MELISSA (DNR)
Cc: STRICKLER, TIM (DNR)
Subject: RE: creostote

She mentioned that it was under water at high tide, but did not give an approximate tidal level. I just left her a message to get back to me.

Derrick

From: FERRIS, MELISSA (DNR)
Sent: Wed 10/6/2010 11:43 AM
To: KOZAK, KEVIN (DNR); TOBA, DERRICK (DNR)
Cc: STRICKLER, TIM (DNR)
Subject: RE: creostote

Derrick, did you ask the coast guard contact where the pipe is on the property?

Melissa Ferris

Program Manager
Derelict Vessel Removal Program, Aquatic Resources Division
Washington State Department of Natural Resources
(360) 902-1574
melissa.ferris@dnr.wa.gov
www.dnr.wa.gov

From: KOZAK, KEVIN (DNR)
Sent: Wednesday, October 06, 2010 11:41 AM
To: TOBA, DERRICK (DNR); FERRIS, MELISSA (DNR)
Cc: STRICKLER, TIM (DNR)
Subject: RE: creostote

Hello,

Tim Strickler is better prepared to answer this question. I have forward you information to him.

Kevin

Kevin Kozak
GIS Analyst
Aquatic Resources

Washington Department of Natural Resources (DNR)
(360) 902-1164
kevin.kozak@dnr.wa.gov
www.dnr.wa.gov

From: TOBA, DERRICK (DNR)
Sent: Wednesday, October 06, 2010 11:14 AM
To: KOZAK, KEVIN (DNR)
Subject: FW: creostote

Kevin,

Here is a physical address for the site of the leak.

Derrick

From: FERRIS, MELISSA (DNR)
Sent: Wed 10/6/2010 10:49 AM
To: TOBA, DERRICK (DNR)
Cc: SWENDDAL, KRISTIN (DNR); COTHERN, SHAYNE (DNR)
Subject: creostote

Note that this site is part of the Ecology Confirmed & Suspected Contaminated Sites List.

Site Name: OLD BREMERTON GASWORKS & SESKO PROPERTY **Entered Date** September 22, 1994

FS ID: 2641	Rank	1	Last Update	December 14, 2009	
Address	1725 PENNSYLVANIA AV	PSI	Resp. Unit	Headquarters	
	BREMERTON, WA 98310	VCP	Ecology Status	Ranked, Awaiting RA	
(View Map)	Lat: 47.57705 / Long: -122.64211		Brownfield		
<u>Contaminant</u>					

ACTIVITY

STATUS

START

END

LEGAL

Site Discovery/Report Received

C

7/15/1993

7/20/1993

Initial Investigation

C

8/24/1993

4/11/1994

Early Notice Letter(s)

C

9/23/1994

9/23/1994

Site Hazard Assessment

C

4/12/1995

6/29/1995

Hazardous Sites Listing

C

8/22/1995

8/22/1995

Remedial Investigation/Feasibility Study

P

7/2/2010

12/31/2010

Media

1

3

7

8

11

Soil- C

C

S

S

C

C

Groundwater- S

S

S

S

S

S

Surface Water- S

S

S

S

S

Sediment- C

S

S

C

Melissa Ferris

Program Manager

Derelict Vessel Removal Program, Aquatic Resources Division

Washington State Department of Natural Resources

(360) 902-1574

melissa.ferris@dnr.wa.gov

www.dnr.wa.gov